


9832-0



9832-0 sudoFIT-Accouplement rapide
sans robinet à bille.
Ne pas utiliser pour des applications permants!

| G | d | Mat. | Art. Nr |
|-----|----|--------|------------|
| 1/2 | 15 | Laiton | 9832.01507 |
| 1/2 | 16 | Laiton | 9832.01607 |
| 1/2 | 18 | Laiton | 9832.01807 |
| 1/2 | 22 | Laiton | 9832.02207 |
| 1/2 | 28 | Laiton | 9832.02807 |
| 1/2 | 35 | Laiton | 9832.03507 |